# Test Report

SGS-CSTC Standards Technical Services（Shanghai) Co., Ltd.

No. 588 West Jindu Rd, Xinqiao Town,

Songjiang District, 201612 Shanghai, CHINA

Tel：+86 21 6191 5666

Fax：+86 21 6191 5600

| | | |
|---|---|---|
| **Report No............................:** | SHESO09120170401 | |
| Date of issue............................: | 2010-01-11 |  |
| **Applicant name...................:** | Ninghai Xidian Wanfeng Plastic Electrical Appliance Factory | |
| Address................................: | Shuangshan, Xidian Town, Ninghai, Zhejiang, China | |
| Manufacturer........................: | Not provided | |
| Address..............................: | Not provided | |
| **Product Description...............:** | LED Shower | |
| Model No...........................: | WF-901 | |
| Date of receipt of test item......: | 2009-12-30 | Picture |
| Date(s) of performance of test.............................: | 2009-12-30 to 2010-01-11 | |
| **Test requirement.................:** | IPX8 test according to client's request | |
| Standard............................: | Refer to IEC60529:2001 | |
| Remark.............................: | None | |

Tested by:  Crystal Yu                                   Date: 2010-01-11

Checked by: Lola Yuan                                   Date: 2010-01-11

We have tested the submitted sample(s) as requested and the following results were obtained:

**Test Information:**

| Test Property | Test Method | Test Description | Test result |
|---|---|---|---|
| IPX8 | Lowest point of enclosure is located 2000 mm below the surface of the water.<br><br>Test duration: 30 minutes.<br><br>Water temperature didn't differ from equipment by more than 5 K. | No water was found depositing inside the enclosure. | Pass |

![SGS logo]

**Annex 1:**

## PHOTO DOCUMENTATION

Before Test



Before Test



After Test of IPX8



After Test of IPX8



After Test of IPX8



After Test of IPX8



**\*\*\* End of Report\*\*\***